



Motorola V551 Screen Replacement

Written By: gregatron



INTRODUCTION

This guide is for removing the screen for the Motorola V551. A flat dental tool may be helpful for step 5 but is not necessary.



TOOLS:

- [Spudger](#) (1)
 - [T6 Torx Screwdriver](#) (1)
 - [iFixit Opening Tools](#) (1)
-

Step 1 — Screen



- Using a spudger, remove the four rubber covers from over the screws.

Step 2




- Unscrew the cover screws using the T6 bit

Step 3






- Loosen and remove the cover with a plastic opening tool.

Step 4



- Gently loosen the protective cover with the plastic opening tool.




Step 5



Carefully remove the protective cover from the circuitry

- Slowly peel the black rubber gasket up off the circuit board.
- Carefully move the camera out of the way using your hand.
- Use a flat tool to separate the connection between the upper and lower circuit boards.

Step 6



- Gently slip the copper strip out from under the circuitry by hand.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-09-15 06:08:15 AM.